The Boeing Company P.O. Box 3707 Seattle, WA 98124-2207 Dry received 3/9/25 12.3.17

March 7, 1995 9-4180-CMB-069D RECEIVED

MAR - 9 1995

DEPI. UF ECOLOGY

Washington State Department of Ecology Northwest Regional Office 3190 160th Ave. S.E. Bellevue, WA 98008-5452

BOEING

Attention: Dean Yasuda

**Environmental Engineer** 

Subject:

Oxbow Site Independent Remedial Action Report

Enclosed is a copy of an independent remedial action report for the clean-up of boiler fuel at the Boeing Oxbow Corporate Park as discussed between you and Rob Bonnett on March 7, 1995. Approximately 1.5 cubic yards of soil were removed and the clean-up level used was the Model Toxics Control Act Method A level of 200 ppm. This project is considered to be completed and no further action will be taken by Boeing.

If you have any questions please call Carl Bach at 544-1225.

A. B. Wipplinger

Environmental Engineering Manager

Boeing Defense & Space Group M/S 4H-26 Phone: 544-6167

Enclosure

USEPA SF

1185461